

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bitu Express			
Report Date: 31-Mar-2023			
Location: STBD AFT LIFE-RAFT			
Unsafe Act Or Condition:			
Type: Unsafe Condition			
Brief Details: AFTER ABANDONSHIP DRILL AFT STBD LIFE-RAFT GUARD RAIL CHAIN WAS NOT SECURED BACK IN POSITION			
Was action taken at the time? :	Yes		
Was work stopped? :	No		
Officer notified?:	Yes		
Action successful? :	Yes		
Report anonymous? :	Yes		
Any other comments or suggestions? Enter below:			
Brief Details: Good observation and all crew must be reminded to secure back all items in place after the drill.			
Date Reviewed by DPA : 06-Apr-2023			
Actions:			
Tick further Actions : No Further action required Remarks :			
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed: Yes			

Unsafe Act or Condition Printed On: 27-Sep-2023 1/1