

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bitu Express		
Report Date: 31-Mar-2023		
Location: STBD AFT LIFE-RAFT		
Unsafe Act Or Condition:		
Type: Unsafe Condition		
Brief Details: AFTER ABANDONSHIP DRILL AFT STBD LIFE-RAFT GUARD RAIL CHAIN WAS NOT SECURED BACK IN POSITION		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified?:	Yes	
Action successful? :	Yes	
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details: Good observation and all crew must be reminded to secure back all items in place after the drill.		
Date Reviewed by DPA : 06-Apr-2023		
Actions:		
Tick further Actions : No Further action required Remarks :		
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed: Yes		

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1