



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu River			
Report Date : 06-May-2023			
Location : PURIFIER ROOM			
Unsafe Act Or Condition:			
Type : Unsafe Act			
Brief Details : THE CREW FOUND LIFTING THE HEAVY WIEGHT INSTEAD USING CHAIN BLOCK.			
Was action taken at the time? :	Yes	THE OFFICER IN CHARGE FOR THE DUTY ORDERED TO STOP THE JOB & ARRANGED THE CHAIN BLOCK TO LIFT THE SAME.	
Was work stopped? :	Yes	THE OFFICER IN CHARGE FOR THE DUTY ORDERED TO STOP THE JOB & ARRANGED THE CHAIN BLOCK TO LIFT THE SAME.	
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous? :	No		
Any other comments or suggestions? Enter below:			
Brief Details : Good observation, concur with action plan.			
Date Reviewed by DPA : 11-May-2023			
Actions :			
Tick further Actions :	No Further action required	Remarks :	Discuss the lifting techniques during next safety meeting,
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed : Yes			