



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu River		
Report Date : 08-Feb-2023		
Location : ENGINE		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : ECR SAFETY LOCKER FOUND THE DIRTY BOILER SUIT INSIDE.		
Was action taken at the time? :	Yes	BOILER SUIT REMOVED FROM LOCKER.
Was work stopped? :	No	BOILER SUIT REMOVED FROM LOCKER.
Officer notified? :	Yes	ACTION TAKE BY THE OFFICER ON SITE.
Action successful? :	Yes	ALL CREW INSTRUCTED NOT TO KEEP ANY ITEMS IN LSA LOCKERS. ADVISED LSA AND FFA ITEMS TO BE READY FOR USE ALL TIME.
Report anonymous? :	Yes	ACTION TAKE BY THE OFFICER ON SITE.
Any other comments or suggestions? Enter below:		
Brief Details : Importance of securing must be discussed with all crew members, Safety lockers must be maintained in neat and tidy condition at all times.		
Date Reviewed by DPA : 15-Feb-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		