



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Bitu River		
Report Date : 21-Apr-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : While removing the razor wire to deploy pilot ladder for access the razor wire was left unsecured near embarkation access. This could result in injury to persons coming on/off the vessel.		
Was action taken at the time? :	Yes	Razor wire stowed in its respective location.
Was work stopped? :	Yes	Razor wire stowed in its respective location.
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Good housekeeping must be maintained at all times. Ensure all access are maintained uninterrupted at all times.		
Date Reviewed by DPA : 28-Apr-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		