



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Demerara		
Report Date : 14-May-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : During the routine patrol on the deck before the ship's departure, it was noticed that a lashing from the anchor was rusty and in poor condition		
Was action taken at the time? :	Yes	Master informed
Was work stopped? :	Yes	Master informed
Officer notified? :	Yes	
Action successful? :	Yes	Replaced
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details : Concur with action plan. Anchor lashing must always be maintained in good condition.		
Date Reviewed by DPA : 17-May-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		