



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Demerara		
Report Date : 29-Aug-2023		
Location : Surinam anchorage		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : While heaving up the anchor, and starting the fire pump for anchor wash, it was observed that no water is coming on the washing line. Where as the Discharge pressure at Pump was in range. After investigation it was found that deck isolation valve for FiFi line was closed, same was opened immediately and anchor wash was carried out. After maneuvering, entire crew was briefed about the significance and effect about closing valve without proper information to both the departments Deck as well as Engine. The act resulted as no water for anchor wash and no water in the fire line for accomodation area.		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details :		
Date Reviewed by DPA : N/A		
Actions :		