



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

Vessel : Morbihan		
Report Date : 12-Feb-2023		
Location : AT FDF BERTH		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : AFTER BERTHING DURING SAFETY INSPECTION, OFFICER NOTICED THAT SOME SCUPPER PLUGS WERE NOT PLACED IN SCUPPERS.		
Was action taken at the time? :	Yes	CREW WAS CALLED AND INSTRUCTED TO MAKE SURE THAT ALL THE SCUPPER PLUGS ARE IN PLACE BEFORE ARRIVAL AT BERTH.
Was work stopped? :	No	CREW WAS CALLED AND INSTRUCTED TO MAKE SURE THAT ALL THE SCUPPER PLUGS ARE IN PLACE BEFORE ARRIVAL AT BERTH.
Officer notified? :	Yes	HELD SHORT DISCUSSION.
Action successful? :	Yes	CREW WERE UNDERSTOOD AND ACTED ACCORDINGLY.
Report anonymous? :	No	HELD SHORT DISCUSSION.
Any other comments or suggestions? Enter below:		
Brief Details : Good observation and concur with action plan.		
Date Reviewed by DPA : 16-Feb-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		