



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Morbihan		
Report Date : 20-Sep-2023		
Location : At FDF pilotage		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : During last port of call to FDF, when pilot come onboard, he raises a concern to master regarding pilot ladder poor condition.		
Was action taken at the time? :	Yes	Deck crew replace the starboard side pilot ladder t which is in poor condition to with port side pilot ladder of which condition is better than the starboard side ladder.
Was work stopped? :	No	Deck crew replace the starboard side pilot ladder t which is in poor condition to with port side pilot ladder of which condition is better than the starboard side ladder.
Officer notified? :	No	
Action successful? :	No	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Vessel must maintain pilot ladder in good condition at all times. A poor condition of pilot ladder poses a huge risk to the pilot while used for pilot transfer.		
Date Reviewed by DPA : 29-Sep-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		