Vessel : MT. BITU ATLANTIC Location:COSCO SHIPYARD NANTONG

Date (dd/mm/yy):06.10.2018

Type of Drill :FIRE IN THE PUMP ROOM DRILL (TABLE TOP)

Description of Planned Drill:-

PROPER TRAINING TO ALL CREW , ACTION TO BE TAKEN IN CASE OF FIRE IN THE PUMP ROOM

SOLAS Requirements for Conducting Abandon Ship Drill and Fire Drill:

SOLAS Ch III Reg 19 3.3 Requires Abandon Ship Drill Should Include atleast following: -

- Raising of Alarm and Mustering of Crew at Muster stations,
- Preparing for Their Duties as described in Muster List,
- Checking that Crew is appropriately dressed and Life jackets properly donned,
- Lowering of at least one Life boat after necessary preparation, (Not for free fall Life Boats),
- Starting and operating Life boat Engine,
- Operating Davits used for Launching Life rafts,
- Mock search and Rescue of Crew Trapped in Staterooms,
- Instructions in use of Radio Life Saving Appliances.

SOLAS Ch III Reg 19 3.4 Requires Fire Drill Should Include at least following: -

- Fire Drills should be planned so as to have regular practice in various emergencies that may occur depending upon type of vessel,
- Reporting for stations and Preparing for Their Duties as described in Muster List,
- Starting Fire pump using at least 2 jets of water,
- Checking of fireman's outfit and other personal rescue equipments,
- Checking operation of water tight doors, fire doors, fire dampers and ventilation systems in area of drill,
- Check necessary arrangements for subsequent abandoning of the ship.

Log Of Events Of Drill: - Each and every reported event to Bridge has to be recorded with time as below: -

After initial Alarm Sounded crew muster at Emergency Muster Station: -

Time	Event	Reported By
17:10	Alarm Sounded, Nature of drill declared by Master: FIRE IN THE PUMP ROOM DRILL	MASTER
17:11	Crew Mustered	CH.OFF
17:12	Head Count Taken- Missing PersonsNONE	CH.OFF
17:14	Checking of PPE Done	CH.OFF
17:15	Duties Checked / Explained	CH.OFF

Master declares the nature of emergency and Emergency team Organisation done as below: -

Time	Event	Reported By
17:18	Table Top Drill conducted on the topic FIRE IN THE PUMP ROOM	CH.OFF
	by C/OFF .	
	Discussed that in such a case ship fire party to be standby, if major fire all personel to be evcuated.	CH.OFF
	Shipyard authorities to be informed for assiting in fire fighting & ship should moved or towed away from the dock.	CH.OFF

To be completed on conclusion of every drill & forwarded by Email at end of every month & filed as hard copy on board in Bridge 5.20 folder Maritec N.V.

B. 5.20 - DRILL REPORT

Date: 01/06/2018Page:2 of 3Made by:QHSEApproved by :MDRev. No:01

	Discussed about fire wire, methods of rigging fire wire.	CH.OFF
	Q & A Session carried out .Crew debriefed by chief officer.	CH.OFF
	Crew understanding and response satisfactory	CH.OFF
17:38	Drill called off by master	
		·

Evaluation Of Drill for improving the training and response of crew in emergency:- This Should be based upon follwoing: -

- Response of Crew in Drill as observed by all Team Leaders and Master,
- Feedback from Crew Members for effective improvemnet of Response,
- Identification for Further training requirements should be aimed for improvement.

ALL SATISFACTORY

Drill Attendance Log:-

Sr. No	Name	Rank
1	CAPT. PANAIT MARIN	MASTER
2	GURDAS SINGH	CH.OFF
3	SILVESTRE A FERNANDES	3RD OFF
4	ANDRIESANU DUMITRU	CH.ENG
5	ANGELADA ARSENIO JR. CERVANTES	2ND ENG
6	PASCUAL HERWIN CELORICO	3RD ENG
7	MARTINEZ LEOLOR ADAM BEQUILLA	4TH ENG
8	KARTHIKEYAN KRISHNAN MOOKIA	ELEC.OFF
9	PRUDENTE GERALD GAITE	BOSUN
10	BAILO LYNDON BANDOLA	PUMPMAN
11	LUMAWAG JEFFREY RIEGO	AB-1
12	ADI VENANCIO MONDEJAR	AB-2
13	DE MESA JOE VENSON	AB-3
14	AMPOLOQUIO LEO RABI	OS-1
15	PAJO JIMBOY VILLANUEVA	OS-2
16	SHUKLA SUNIL KUMAR	FTR-1
17	SILIGAN GREGORIO JR.	FTR-2
18	LABRADOR RYAN AROLLADO	OILER-1
19	SEBUCO MARK ANTHONY EMBOLODE	OILER-2
20	SIBAYAN DENNIS	CH.COOK
21	BAUTO JERWIN CHUAHAP	MESSMAN
22	SHARMA GAGANDEEP	ELEC.SUPT

To be completed on conclusion of every drill & forwarded by Email at end of every month & filed as hard copy on board in Bridge 5.20 folder Maritec N.V.

23	
24	
25	
26	
27	
28	

Safety Officer : - Name: GURDAS SINGH

Master : - Name: CAPT. PANAIT MARIN