

## B. 14.0 - RISK ASSESMENT FORM

Date	: 10/08/2018
Page	: 1 Of 1
Made By	: QHSE
Approved By	: MD
Rev No	: 0

## Risk Assessment

	RA No : B001/2018	Description of Task: Enclosed Space entry	Date : 22.10.2018
No.	Hazards	Existing Measures / Safeguards in Place	Additional Measures to Mitigate Risk
1	There is lack of communication between the stand-by and the person(s) entering inside the spac	ISM form B.7.30 , B.7.30 , CCR.5.20, CCR5.30	Communication provided at entrance and with OOW and persons working
2	The space to enter is dirty / slippery	ISM form B.7.30 , B.7.30 , CCR.5.20, CCR5.30	ventilated and dry.
3	The space is not/or adequately lighted	ISM form B.7.30 , B.7.30 , CCR.5.20, CCR5.30 0	Have adequate light.
4	The space is not/or adequately ventilated	ISM form B.7.30 , B.7.30 , CCR.5.20, CCR5.30	Have adequate ventilation.
5	The space is overheated (above 50°C)	Ref.code of Safe working practices	Entry in overheated enclosed spaces should be prohibited, until temperature drops in sustainable levels
6	Access means/ internal structural members failure due to bad cond.	ISM form B.7.30 , B.7.30 , CCR.5.20, CCR5.30	Condition of strength members good.
7	The rescue & resuscitation	ISM form B.7.30 , B.7.30 , CCR.5.20, CCR5.30	Ready at entrance.
8	The vessel is rolling / pitching		Calm weather./alteration of course
9	The person carrying out the job is not provided with P.P.E.	ISM form B.7.30 , B.7.30 , CCR.5.20, CCR5.30	All personnel working have PPE.
10	Tools / equipment used, not checked for "non-sparking"	Ref.code of Safe working practices	Tools / equipment used checked for "non-sparking"

Hazard				Exist	ing M	easur	es		Additional Control Measures											
No.		onse (How	quen / Bad		Probability (How Often)				Risk Factor	C		quend / Bad)			Risk Factor					
1	a	) (a) (b)		•	O O O		2	a	<b>©</b>	O O+		•	Q	O	O#	2				
2	a	<b>©</b> 2	O	O#	•	Q	C	O	2	a	<b>©</b>	O	O#	•	Q	O	O#	2		
3	O	<b>@</b>	O	Œ	<b>(1)</b>	Œ	O	O	2	O	<b>©</b> 2	O	Œ	<b>(1)</b>	O2	O	Œ	2		
4	а	Q	<b>③</b>	O#	Q	Q	<b>®</b>	O	9	а	Q	<b>③</b>	O#	Q	<b>®</b>	O	O+	6		
5	O	<b>©</b>	C	Œ	<b>(1)</b>	Q	C	Œ	2	O	<b>©</b> 2	O	Œ	<b>(1)</b>	O2	O	Œ	2		
6	<b>①</b>	Q	O	O#	•	Q	O	O	1	<b>①</b>	Q	O	O#	•	Q	O	O#	1		
7	•	O.	O	Œ	<b>(1)</b>	O.	O	Œ	1	O	<b>©</b> 2	O	Œ	•	O2	O	Œ	2		
8	a	<b>@</b>	O	O#	•	Q	C	O	2	a	<b>©</b>	O	O#	•	Œ	O	O#	2		
9	<ul><li>Q</li><li>Q</li><li>Q</li></ul>		•	œ	O	O#	1	Ó	<b>©</b> 2	O	O#	•	O	O	Œ	2				
10	0 0 0 0 0 0 0 0 0					a	<b>©</b>	O	O#	•	Q	Œ	O#	2						
		<b>I</b> ►NE	GLIGII	SIE		► MC	DEBA	TE	_		► SIC	MIEIC	ANIT	NINTOLEPARIE						

	3	5	•	3	5	Ď	5	3	5	2	5	•	3	5	Ď	4	ď	<b>\</b>	2					
	4	а	Q	<b>®</b>	O#	а	Œ	<b>®</b>	O#	9	a	œ	<b>③</b>	O#	O	<b>©</b>	Ö	<b>O</b> #	6					
	5	O	<b>@</b>	O	Œ	<b>(</b>	O.	O	Œ	2	O	<b>@</b>	O	Œ	•	O	O	Œ	2					
	6	<b>(</b>	Q	O	Œ	•	Q	O	Œ	1	•	Q	O	O	•	Q	O	O+	1					
	7	<b>(</b>	Q.	O	Œ	•	O.	C	Œ	1	O	<b>@</b>	O	Œ	•	O <sup>2</sup>	O	Œ	2					
	8	a	<b>@</b>	O	Œ	•	Œ	C	Œ	2	a	<b>©</b>	O	Œ	•	O2	O	O#	2					
	9	•	Q.	O	Œ	<b>(</b>	O <sub>2</sub>	O	Œ	1	Ö	<b>@</b>	O	Œ	•	O <sup>2</sup>	O	Œ	2					
	10	a	<b>@</b>	O	0#	•	Q	O	O#	2	đ	<b>@</b>	Ö	O#	•	O	Ö	O#	2					
			►NE	GLIGIE	BLE		►MO	DERA	TE			►SIG	SNIFIC	ANT		►INT	OLER	ABLE						
Remarks:	Monito	oring	is re	quire	d to e	ensur	e tha	t the	cont	rols are	mai	ntain	ed.											7
Note: -	If control measures are insufficient to mitigate risk to acceptable level, the task must be postponed or cancelled and the company to consulted.															y to be								
BITU ATLANTIC : MOHSIN MUILLA, 2ND OFF, 14/01/2019								Risk Assessment Approval:									Proceed							
Ship: - Name, Rank, Date																	Not	to Proc	eed:					
(Note: This Approval is Subject to all the above conditions being maintained all throughout till final completion of task)  Office: - Name, Rank, Date																								