



Maritec Tanker Management Private Limited

Incident Reports Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga	Defect ID : 152	NCR # : 19/2023	Is NCR ? : Yes
--------------------------	-----------------	-----------------	----------------

Defect Details

AT AGIOS THEODOROI, ON 4TH AUGUST DURING VISIT BY PSC INSPECTOR IT WAS FOUND THAT STBD SIDE FIRE DAMPER OF FUNNEL WAS NOT CLOSING PROPERLY.

Requisition Code :

Categories

Primary :	Incident	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Safe Working Procedures not Followed	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 04-Aug-2023	ETC : 06-Aug-2023	Date Completed : 05-Aug-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Vessel	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 03/Oct/2023

Causes

CLOSING PISTONS WERE SLOW TO RESPOND

Corrective Action

NEED MORE LUBRICATION

Preventive Action

NEED TO REPLACE THE ACTUATORS BY NEW ONE

CONTRIBUTING FACTORS

Follow Up


On	By	Follow Up	
05/Aug/2023	Asfaha Tekeste Gebremichael Staff Code - 10368 - MST	AWAITING OFFICE ACTION for this job has been changed to Yes	

Before & After Pictures

Before	After
--------	-------




Notification

 File Not Uploaded




Notification

 File Not Uploaded




Notification

 File Not Uploaded



Notification

 File Not Uploaded