

Maritec Tanker Management Private Limited

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Incident Reports Details

Vessel : Asphalt Teranga Defect ID : 203 NCR # : 44/2023 Is NCR ? : Yes

Defect Details

Today 14.12.2023 at 16:00 (+-5min) incident have happened with Fitter in ship's workshop. His right thumb was badly injured, almost cut out during working on the lathe machine. He was send to shipyard medical point and after that to city hospital. 2nd officer accompained him.

Requisition Code:

Categories							
Primary :	Incident	Inspector - Internal:		Vessel Dept:	Engine		
Secondary :	Safe Working Procedures not Followed	Inspector External :		Office Dept:	Safety		
		Inspection Date :					

Applicable Dates

Date Raised: 14-Dec-2023 ETC: 31-Jan-2024 Date Completed:

Other Details						
Priority : Urgent	Assigned By: Vessel	Verified By :				
Display in Daily Meeting? : No	SFI:	Verified On:				

Causes

Corrective Action

Preventive Action

CONTRIBUTING FACTORS

Follow Up

On	Ву	Follow Up	
19/Dec/2023	Nawin Khaware	Put the details under causes, corrective action and preventive action. Additionally, pull out the drop down menu for Applicable tags and select the applicable boxes. Once done then confirm.	
18/Dec/2023	Cristian Ion Petrache Staff Code - 10566 - MST	Priority for this job has been changed from to URGENT	

Before & After Pictures

Incident Reports Details Printed On: 19-Dec-2023 1/2