

Maritec Tanker Management Incident Report's Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel:	Bahama Blue	Defect ID: 184	NCR # : 6/2023	Is NCR ?: Yes

Defect Details

Before loading at St. Croix Cargo Officer checked and tested all equiptment as per CCR.2.10,2.11 and found out that Independent Overfill & High Level Alarm system is not working on deck.

Requisition Code:

Categories					
Primary :	Incident	Inspector - Internal:		Vessel Dept:	Deck
Secondary :	Other	Inspector External :		Office Dept:	Safety
		Inspection Date :			

Applicable Dates

Other Details

Priority: Normal Assigned By: Vessel Verified By:

Display in Daily Meeting? : No SFI: Verified On :

Causes

Corrective Action

Preventive Action

Applicable Tags

Descriptions

Machinery / Equipment Damage

Follow Up

On	Ву	Follow Up	
02/Jun/2023	Valentin MITENKOV Staff Code - 10552 - MST	NCR is still open. ETO joined vessel on 25.05.2023 and working to solve problemm.	

Before & After Pictures

Before	After

Incident Report's Details Printed On: 05-Jun-2023 1/1