



Maritec Tanker Management

Non Conformance Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Morbihan	Defect ID : 82	NCR # : 4/2023	Is NCR ? : Yes
-------------------	----------------	----------------	----------------

Defect Details

Compressor Controller (Human Interface) is defective. Compressor can not be used in AUTO Mode and there is no indication of the compressor parameters as the display is completely "black". For the moment, in case of need, we are starting the compressor in emergency mode. Compressor No1 is also the Emergency Compressor being powered from the ESB.

Requisition Code : MORB-SOT-V230115

Categories

Primary :	E/R Machinery	Inspector - Internal :		Vessel Dept :	Electrical
Secondary :	Electrical equipment	Inspector External :		Office Dept :	Technical
		Inspection Date :			

Applicable Dates

Date Raised : 07-Apr-2023	ETC : 14-Apr-2023	Date Completed : 17-Jul-2023
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : Vessel	Verified By :
Display in Daily Meeting? : No	SFI :	Verified On :

Causes

Wear of equipment

Corrective Action

Replace display

Preventive Action

Display to be available OB as spare

Applicable Tags

Follow Up

On	By	Follow Up	
17/Jul/2023	Octavian Marius Surlea Staff Code - 10503 - C/E	New HMI received on 16/07.2023 and installed in position. Compressor is running in normal parameters at the moment.	Link1 Link2

Before & After Pictures

Before	After
--------	-------

