



Maritec Tanker Management Private Limited

Non Conformance Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra	Defect ID : 194	NCR # : 6/2024	Is NCR ? : Yes
-----------------	-----------------	----------------	----------------

Defect Details

15 PPM alarm arrangement defective.

Requisition Code :

Categories

Primary :	E/R Machinery	Inspector - Internal :		Vessel Dept :	Engine
Secondary :	Miscellaneous	Inspector External :		Office Dept :	Technical
		Inspection Date :	20-Apr-2023		

Applicable Dates

Date Raised : 18-Apr-2023	ETC : 20-Apr-2023	Date Completed : 20-Apr-2024
---------------------------	-------------------	------------------------------

Other Details

Priority : Urgent	Assigned By : Port State Control	Verified By : Nawin Khaware
Display in Daily Meeting? : No	SFI :	Verified On : 05/Jul/2024

Causes

Inadequate maintenance with no proper routine checks in place.

Corrective Action

Trouble shooting and repair/replacement of defective part will be carried out. If required, requisition will be raised for same.

Preventive Action

Proper routine maintenance and routine test should be maintained at all time as per company procedures.

CONTRIBUTING FACTORS

Descriptions

Pollution

Root Causes- Job Factor

Inadequate Maintenance

Direct Causes- Unsafe Acts

Failure to Follow Repair / Maintenance Instructions

Follow Up

On	By	Follow Up	
Before & After Pictures			
Before		After	