



Maritec Tanker Management

Non Conformance Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 73	NCR # : 4/2020	Is NCR ? : Yes
------------------------	----------------	----------------	----------------

Defect Details

11101 Operating instructions for Lifeboat STBD not readable

Requisition Code :

Categories

Primary :	Near Miss	Inspector - Internal :		Vessel Dept :	Deck
Secondary :	Lack of Supervision / Leadership / Planning	Inspector External :		Office Dept :	Safety
		Inspection Date :			

Applicable Dates

Date Raised : 21-Mar-2020	ETC : 28-Mar-2020	Date Completed : 21-Mar-2020
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Port State Control	Verified By : Rakesh Kumar
Display in Daily Meeting? : No	SFI :	Verified On : 21/Mar/2020

Causes

Operating instructions provided on Metal as engraving at time of delivery was obsolete but not removed. IMO and Ship's stenciled instructions were in place at the time on inspection.

Corrective Action

All obsolete labels removed from around the ship.

Preventive Action

Crew to make aware that if a label is obsolete/old is to be concealed/removed.

Applicable Tags

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before	After
--------	-------

