



Maritec Tanker Management Private Limited

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Kensington LG

Defect ID : 42

Defect Details

During inspection of vegetable room, a crew was inspecting the vegetable room evaporator. After the inspection, the door does not respond to open when he was trying to get out. Immediately, he presses the alarm inside and a crew from the galley was responding and opened him.

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Engine
Secondary :	Other	Office Dept :	Technical

Applicable Dates

Date Raised : 02-Nov-2023

Date Completed : 02-Nov-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	03/Nov/2023
Potential to become a serious accident : Low			Recurrence : Low		

Causes

Door handle mechanism fails to open from inside but operational at outside.

Corrective Action

Immediately rectify the problem by fixing the door mechanism

Preventive Action

To check daily operation once before entering

CONTRIBUTING FACTORS

Substandard Conditions

Defective Materials

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before



After

