

Maritec Tanker Management Private Limited

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A

Rev Date

: N/A

Near Miss Details

Gui	ı	an	00
Gu	ıu	an	UE.

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Atlantic Defect ID: 299

Defect Details

Pumproom permit was not available at time of entry. Pumproom permit was made without checking gases, meter at top of pumproom inoperational

Requisition Code:

Categories			
Primary:	Near Miss	Vessel Dept :	Deck
Secondary :	Procedures not Followed	Office Dept:	Operations

Applicable Dates

Date Raised: 08-Aug-2023 Date Completed: 21-Aug-2023

Other	Details

Priority :	Urgent	QMS Elements Ref :	CCR. 5.3 - Pump Room Entry Permit	Verified By :	Fiacre Fonseca
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	18/Sep/2023

Potential to become a serious accident : - SELECT- Recurrence : - SELECT-

Causes

Corrective Action

Preventive Action

CONTRIBUTING FACTORS

Job Factors

Inadequate Procedure or Checklist

Follow Up

On	Ву	Follow Up	
21/Aug/2023	Cosmin Otelea Staff Code - 10502 - C/OFF	Pumproom permit was issued after proper checks.	

Near Miss Details Printed On: 14-Dec-2023 1/2

Before & After Pictures

Before

After



