



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu River

Defect ID : 26

Defect Details

The SOPEPE box near manifold was not lashed properly and the latch was found damaged which could result in loss of items, damage to box in case of rough weather or rolling.

Requisition Code :

Categories

Primary :

Near Miss

Vessel Dept :

Deck

Secondary :

Other

Office Dept :

Safety

Applicable Dates

Date Raised : 11-Apr-2023

Date Completed : 12-Apr-2023

Other Details

Priority :

Normal

QMS Elements Ref :

- SELECT -

Verified By :

Nawin Khaware

Show in Monthly Safety Meeting? :

No

SFI :

Verified On :

26/May/2023

Potential to become a serious accident : Low

Recurrence : Low

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On

By

Follow Up

Before & After Pictures

Before

After

