

Maritec Tanker Management Private Limited

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.										
Vessel : Asphalt Teranga				Defect ID : 199						
Defect Details										
UNSAFE PPE										
Requisition Code :										
Categories										
Primary :	Near Mi	Near Miss		Dept :	Deck					
Secondary :	Imprope	Improper PPE		Dept :	Safety					
Applicable Dates										
Date Raised : 15-Nov-2023				Date Completed : 19-N	Nov-2023					
Other Details										
Priority :	Normal	QMS Elements	Ref :	- SELECT -	Verified By :	Nawin Khaware				
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :	20/Nov/2023				
Potential to become a serious accident : Medium Recurrence : Medium										
Causes										
ONE CREW WAS FOUND WITH OVERAL IN BAD CONDITION										
Corrective Action										
AB RECEIVED NEW OVERAL										
Preventive Action										
CHECK ALLCREW THAT HAVE ENOUGH AND IN GOOD CONDITION PPE										
CONTRIBUTING FACTORS										
Direct Causes- Unsafe Acts										
Failure to Use PPE Properly										
Personal Factors										
Lack of Knowledge										
Substandard Conditions										
Inadequate or Improper PPE										

Follow Up								
On	Ву	Follow Up						
Before & After Pictures								
Before			After					