



# Maritec Tanker Management

## Near Miss Details

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

**Guidance:**

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu Atlantic

Defect ID : 282

### Defect Details

Noticed, Galley to officer mess room fire door kept open and fasten with rope. Immediately removed the rope and closed the self closing fire door.

Requisition Code :

### Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Lack of Situational Awareness	Office Dept :	Crew

### Applicable Dates

Date Raised : 26-Jul-2023

Date Completed : 26-Jul-2023

### Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	
Potential to become a serious accident : Low			Recurrence : Low		

### Causes

### Corrective Action

### Preventive Action

### Applicable Tags

### Root Causes- Management Factors

Inadequate Procedures / Checklists

### Root Causes- Personal Factor

Situational Awareness

### Follow Up

On	By	Follow Up	
----	----	-----------	--

02/Aug/2023	Nawin Khaware	Provide complete details under CA/PA/causes and also provide details under applicable tags and then make the submission for our review.	
-------------	---------------	---	--

**Before & After Pictures**

<b>Before</b>	<b>After</b>
---------------	--------------