

Maritec Tanker Management

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Near Miss Details

Gui	Ы	ar	CO.
Gu	ıu	aı	IUE.

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Atlantic Defect ID: 284

Defect Details

Accommodation ladder stencil found fade off, the Max number of person, Max angle and the SWL not visible.

Requisition Code:

Categories						
Primary :	Near Miss	Vessel Dept :	Deck			
Secondary :	Procedures not Followed	Office Dept:	Safety			

Applicable Dates

Date Raised: 27-Jul-2023 Date Completed: 27-Jul-2023

Other Details		
Priority :	Normal	QMS Elements Ref :

- SELECT - Verified By :

Show in Monthly Safety Meeting? :

Verified On:

Potential to become a serious accident : Medium Recurrence : Low

SFI:

Causes

Corrective Action

Preventive Action

Applicable Tags

Root Causes- Personal Factor

High Workload Fatigue

Substandard Acts

Failure to Comply with Manufacturer's Operating Instructions

Failure to observe basic safety rules

Follow Up

Near Miss Details Printed On: 31-Jul-2023 1/2

On	Ву	Follow Up				
Before & After Pictures						
Before		After				

Near Miss Details Printed On: 31-Jul-2023 2/2