

Near Miss Details

Guidance: 01) Please do not mention any names in the near miss report. 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.										
Vessel : Asphalt Teranga				Defect ID : 143						
Defect Details										
OILY RAGES FOUND IN INCINERATOR UNDER THE BURNER PUMP. Requisition Code :										
Categories										
Primary :	Near Mi	Near Miss		Dept :	Engine					
Secondary :	Poor Ho	Poor Housekeeping		Dept :	Technical					
Applicable Dates										
Date Raised : 28-Apr-2023				Date Completed : 05-May-2023						
Other Details										
Priority :	Normal	ormal QMS Elements F		- SELECT -	Verified By :	Nawin Khaware				
Show in Monthly Safety Meeting? :	No	SFI :			Verified On :	26/May/2023				
Potential to become	a serious accio	dent : Low	Recurrence : Low							
Causes										
CARELESSNESS										
Corrective Action										
SAME WAS REMOVED AND TOOLBOX MEETING CONDUCTED WITH ENGINE ROOM CREW										
Preventive Action MEETING CONDUCTED WITH ENGINE ROOM CREW AND INFORMED										
Applicable Tags										
Root Causes- Personal Factor										
Lack of Discipline										
Personal Factors										
Lack of Knowledge										
Substandard Acts										
Failure to observe basic safety rules										

Follow Up								
On	Ву	Follow Up						
Before & After Pictures								
Before			After					