

# **Maritec Tanker Management Private** Limited

Ship File No : N/A Office File No: N/A Form No : N/A : N/A Issue Revision : N/A

: N/A

Rev Date

**Near Miss Details** 

Guidance:
Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Saint James LG Defect ID: 341

## **Defect Details**

On the Top of No. 3 Generator Lamp coverfound broken.

Requisition Code:

Categories			
Primary :	Near Miss	Vessel Dept:	Engine
Secondary :	Inadequate Maintenance / Wear and Tear	Office Dept:	Human Resources

# **Applicable Dates**

Date Raised: 28-Nov-2023 Date Completed: 28-Nov-2023

Other Details					
Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	
Potential to become	a sprious acci	dent : Medium	Recurrence : Low		

Potential to become a serious accident: Medium Recurrence : Low

#### Causes

Because of Vibration.

### **Corrective Action**

Changed Cover with new one.

#### **Preventive Action**

Discussed with Electrician when make rounds check condition of lamps and lamps covers.

## **CONTRIBUTING FACTORS**

Eal	low	ш	-
E = ( 0 1 I	1 [ 0 ] ] [	L W	I 0 1

**Follow Up** On By

## **Before & After Pictures**

**Before After** 

Near Miss Details Printed On: 14-Dec-2023 1/1