

## **Maritec Tanker Management**

## **Near Miss Details**

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

01) Please do not mention any names in the near miss report.

02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet. 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel: Bitu Atlantic Defect ID: 257

## **Defect Details**

During the operation of the ship in the port, the deck watch did not comply with the security measures a/p marsec 2 . Immediately he was notified by the oow and complied with the requirements.

Requisition Code:

Categories				
Primary :	Near Miss	Vessel Dept :	Deck	
Secondary :	Lack of Situational Awareness	Office Dept:	Safety	

Ann	اماممنا		10400
WAN 0 1 0 1	[[042]0]	( <del>-</del>	Dates

Date Raised: 30-Dec-2022 Date Completed: 30-Dec-2022

Other Details					
Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI:		Verified On:	06/Jan/2023

Potential to become a serious accident: Low Recurrence: Low

Causes

**Corrective Action** 

**Preventive Action** 

**Applicable Tags** 

**Root Causes- Job Factor** 

Inadequate Work Standards

**Root Causes- Management Factors** 

Inadequate Procedures / Checklists

**Root Causes- Personal Factor** 

Lack of Knowledge

Near Miss Details Printed On: 14-Jun-2023 1/2

Direct Causes- Unsafe Acts					
Instructions / Orders not Followed					
Follow Up					
On	Ву	Follow Up			
Before & After Pictures					
Before		After			

Near Miss Details Printed On: 14-Jun-2023 2/2