



Maritec Tanker Management

Near Miss Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Guidance:

- 01) Please do not mention any names in the near miss report.
- 02) The confidentiality will be maintained by removing the name of the vessel when the report is circulated to the different vessels in the fleet.
- 03) NOTE: ADDITIONAL INFORMATION IF REQUIRED TO BE ADDED IN A SEPARATE SHEET AND ATTACHED TO THIS REPORT.

Vessel : Bitu Atlantic

Defect ID : 277

Defect Details

Portable ladder not supported / Left unattended while working at height

Requisition Code :

Categories

Primary :	Near Miss	Vessel Dept :	Deck
Secondary :	Procedures not Followed	Office Dept :	Safety

Applicable Dates

Date Raised : 30-May-2023

Date Completed : 06-Jun-2023

Other Details

Priority :	Normal	QMS Elements Ref :	- SELECT -	Verified By :	Nawin Khaware
Show in Monthly Safety Meeting? :	No	SFI :		Verified On :	05/Sep/2023
Potential to become a serious accident : Medium			Recurrence : Medium		

Causes

Lack of supervision.

Corrective Action

Immediately, one safety person was made standby at the ladder to support the worker.

Preventive Action

There have been several incidents in past due working on portable ladder without any safety attendant standing by next to it. hazards associated with same were highlighted to all the crew members and were advised always to keep one safety person stand by next to the portable ladder.

Applicable Tags**Root Causes- Job Factor**

Inadequate Work Standards

Root Causes- Management Factors

Inadequate Monitoring / Supervision

Root Causes- Personal Factor

Lack of Knowledge

Substandard Acts

Failure to follow procedure

Other Unsafe Acts

Follow Up

On	By	Follow Up	
----	----	-----------	--

Before & After Pictures

Before	After
--------	-------

