

Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

Vessel: Morbihan Defect ID: 92 NCR #: Is NCR ?: No

Defect Details

No1 DG Box Cooler Ps is leaking fresh water. In the last few days leakages have become significant.

Today I have isolated the Box Cooler in order to eliminate the fresh water loss, so currently we are running with 3 box coolers. Problem is that for DDC and Kourou we are already facing challenges in order to keep the LT temperature under limits due to all known problems with warming water and mud, so most probably I will need to have this box cooler operational as well. Gasket needs to be replaced. Item No6 gasket is available on board, for item no5 partition gasket I have issued MORB-SOT-V230140.

Please keep in mind that in order to lift the bundle sea water has to be below the mounting ring. I'm not sure if this can be achieved in ballast condition by trimming the vessel. Please see attached pictures.

Requisition Code:

Categories	Categories				
Primary :	E/R Machinery	Inspector - Internal :		Vessel Dept:	Engine
Secondary :	Auxiallary Engines	Inspector External :		Office Dept:	Technical
		Inspection Date :			

Appl	ica	ble	Dat	es

Date Raised: 06-May-2023 ETC: 30-Jun-2023 Date Completed:

Other Details		
Priority : Urgent	Assigned By: Vessel	Verified By :
Display in Daily Meeting? : No	SFI:	Verified On:

Causes

Corrective Action

Preventive Action

Applicable Tags

Follow Up

On	Ву	Follow Up	
23/May/2023	Kamlesh Jalori	ETC has been changed from "15 Jun 2023" to "30 Jun 2023".	
23/May/2023	Kamlesh Jalori	REF MSG FROM VESSEL DATED 18/05 After tightening the FW cover and using the cooler for maneuvering the leakages have diminished. Only small leakage remain on Ps side of the cooler. Box cooler is kept under constant observation.	

Defect List Details Printed On: 19-Jun-2023 1/3

06/May/2023

Octavian Marius Surlea
br/> Staff Code - 10503 -C/E

AWAITING OFFICE ACTION for this job has been changed to Yes

Before & After Pictures

Before



















Defect List Details Printed On: 19-Jun-2023 3/3