

Maritec Tanker Management Defect List Details

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A

: N/A

Rev Date

 Vessel : Bitu Atlantic
 Defect ID : 75
 NCR # : 6/2020
 Is NCR ? : Yes

Defect Details

15150 Standard Text for Action Code 19 (Action Code 17 + detention): Safety Management Audit by the Administration is required before departure of the ship. Deficiency(s) marked ISM is (are) objective evidence of a serious failure, or lack of effectiveness, of implementation of the ISM Code.

Requisition Code:

Categories						
Primary :	Others	Inspector - Internal:		Vessel Dept:	Deck	
Secondary :	Vessel Appearance	Inspector External :	port state control	Office Dept:	Management	
		Inspection Date :	20-Mar-2020			

Applicable Dates

Date Raised: 21-Mar-2020 ETC: 28-Mar-2020 Date Completed:

Other Details					
Priority : Urgent	Assigned By: Port State Control	Verified By :			
Display in Daily Meeting? : No	SFI:	Verified On:			

Causes

Port State found deficiencies not addressed as per ISM

Corrective Action

External ISM Audit to be carried out.

Preventive Action

Training of crew on ISM and SMS to be conducted.

Applicable Tags

Follow Up

On By Follow Up

Before & After Pictures

Before After

Defect List Details Printed On: 16-Apr-2020 1/1