

Maritec Tanker Management

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Defect List Details

Vessel : Bitu	Bitu Atlantic Defect II		: 160	NCR # :	ls N	NCR ? : No	
Defect Details							
T.O.B. Quick closing valve (port side) didn't closed properly while testing was carried out remotely. The reason must be investigated properly and issues must be resolved on priority.							
Requisition Code :							
Categories							
Primary :	E/R Machinery	Inspecto	or - Internal:	Nawin Khaware	Vessel Dept :	Engine	
Secondary :	Miscellaneous	Inspecto	or External :		Office Dept :	Safety	
		Inspecti	ion Date :	27-Sep-2021			
Applicable Dates							
Date Raised : 27-Sep-2021			ETC : 25-Oct-2021		Date Completed : 27-Dec-2021		
Other Details							
Priority : Urgent			Assigned By : HSQE Suptd		Verified By :		
Display in Daily Meeting? : No			SFI :		Verified On:		
Causes							
accumulate dust							
Corrective Action							
periodicaly maintenance							
Preventive Action							
to be clean out and greased							
Applicable Tags							
Follow Up							
On	Ву		Follow Up				
05/Oct/2021 Nawin Khaware							
Before & After Pictures							
Before				After			