

# Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel: Bitu Atlantic Defect ID: 164 NCR #: Is NCR ?: No

#### **Defect Details**

M/E turbocharger exhaust manifold lagging appears in poor condition. To be renewed.

Requisition Code:

Categories							
Primary :	E/R Machinery	Inspector - Internal :	Nawin Khaware	Vessel Dept:	Engine		
Secondary :	Miscellaneous	Inspector External :		Office Dept:	Safety		
		Inspection Date :	27-Sep-2021				

## Applicable Dates

Date Raised: 27-Sep-2021 ETC: 30-Oct-2021 Date Completed: 12-Jan-2022

## Other Details

Priority: Urgent Assigned By: HSQE Suptd Verified By:

Display in Daily Meeting? : No SFI: Verified On :

#### Causes

M/E turbocharger exhaust manifold is in poor condition

#### **Corrective Action**

Clean and paint exhaust manifold and change suction air filter

#### **Preventive Action**

check and keep clean

## **Applicable Tags**

## Follow Up

On	Ву	Follow Up	
31/Dec/2021	Nawin Khaware	Please upload all the evidence to confirm the items are actioned from vessel side.	
05/Oct/2021	Nawin Khaware		

## **Before & After Pictures**

Before	After

Defect List Details Printed On: 04-Apr-2022 1/2



