



Maritec Tanker Management

Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic	Defect ID : 143	NCR # :	Is NCR ? : No
------------------------	-----------------	---------	---------------

Defect Details

Steam dump condenser- frequent chocking of tubes.

Requisition Code :

Categories

Primary :	E/R Machinery	Inspector - Internal :	Vikram Puri	Vessel Dept :	Engine
Secondary :	Auxiliary Equipment	Inspector External :		Office Dept :	Technical
		Inspection Date :	31-Jul-2021		

Applicable Dates

Date Raised : 31-Jul-2021	ETC : 20-Sep-2021	Date Completed : 21-Sep-2021
---------------------------	-------------------	------------------------------

Other Details

Priority : Normal	Assigned By : Tech Suptd	Verified By : Kamlesh Jalori
Display in Daily Meeting? : No	SFI :	Verified On : 22/Oct/2021

Causes

Corrective Action

Preventive Action

Applicable Tags

Job Factors

Other Job Factors

Follow Up

On	By	Follow Up	
26/Sep/2021	Farid Latypov Staff Code - 10227 - 2/E	Steam condenser opened and cleaned. 09 tubes are plugged. Cold repairs carried out on cover using cordobond. Assembled and tested. Working satisfactory.	
27/Aug/2021	Kamlesh Jalori		

Before & After Pictures

Before



After





