

Maritec Tanker Management Defect List Details

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

 Vessel : Bitu Atlantic
 Defect ID : 134
 NCR # :
 Is NCR ? : No

Defect Details

Aft deck are in bad condition due to water carry over from scrubber.

Requisition Code:

| Categories | | | | | | |
|-------------|--------|-----------------------|-------------|--------------|-----------|--|
| Primary : | Others | Inspector - Internal: | Vikram Puri | Vessel Dept: | Deck | |
| Secondary : | Others | Inspector External : | | Office Dept: | Technical | |
| | | Inspection Date : | 31-Jul-2021 | | | |

Applicable Dates

Date Raised: 31-Jul-2021 ETC: 20-Sep-2021 Date Completed: 08-Oct-2021

Other Details

Priority: Normal Assigned By: Tech Suptd Verified By: Kamlesh Jalori

Display in Daily Meeting? : No SFI: Verified On : 08/Nov/2021

Causes

Corrective Action

Preventive Action

Applicable Tags

Direct Causes- Unsafe Conditions

Defective Equipment, Machinery or Tools

Follow Up

| On | Ву | Follow Up | |
|-------------|----------------|-----------|--|
| 26/Aug/2021 | Kamlesh Jalori | | |

Before & After Pictures

Before After

Defect List Details Printed On: 04-Apr-2022 1/2

