



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Asphalt Teranga

Report Date : 07-Jun-2023

Location : LUANDA ANGOLA

Unsafe Act Or Condition:

Type : Unsafe Act

Brief Details : WHEN VESSLE WAS ALONG BERTH PREPARING TO CARRY OUT DISCHARGING OPERATION SENIOR OFFICER DISCOVERED 1 SCUPPER PLUG WAS NOT PLUGGED DECK CREW WAS IMMEDIATELY CALLED AND REINFORMED THEM THE CONSEQUENCES OF NOT PLUGGING ALL SCUPPER.

Was action taken at the time? :	Yes	
---------------------------------	-----	--

Was work stopped? :	No	
---------------------	----	--

Officer notified? :	Yes	
---------------------	-----	--

Action successful? :	Yes	
----------------------	-----	--

Report anonymous? :	No	
---------------------	----	--

Any other comments or suggestions? Enter below:

Brief Details :

Date Reviewed by DPA : N/A

Actions :