

Tick further Actions:

Followup Completed: Yes

Link NC/Observation/Near Miss/ Risk Assessment:

No Further action required

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A

Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Asphalt Teranga Report Date: 11-Jun-2022 Location: LIFEBOAT DECK Unsafe Act Or Condition: Type: Unsafe Act Brief Details: AFTER DOING WEEKLY CHECKS IN LIFEBOAT CREW MEMBER LEFT GUARD RAIL CHAIN OPEN. Was action taken at the time?: Yes Advised crew member to connect guard rail chain to the hooks provided. Was work stopped?: No Advised crew member to connect guard rail chain to the hooks provided. Officer notified?: Yes Action successful?: Yes Gauard rail chain connected back on hook. Report anonymous?: Yes Any other comments or suggestions? Enter below: Brief Details: Good observation. Date Reviewed by DPA: 17-Jun-2022 Actions:

Remarks:

Unsafe Act or Condition Printed On: 26-Sep-2023 1/1