

Vessel : Asphalt Teranga		
Report Date: 15-Jun-2023		
Location :		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : CASE: ONE ENGINE CREW CONTINUES TO WEAR HIS DAMAGE SHOES. ROOT CAUSE: LACK OF SAFE PRACTICE CORRECTIVE/PREVENTIVE ACTION: SEEN BY DUTY ENGINEER HE WAS CORRECTED ON THE SPOT AND BRIEFED AS PER CSWP. HE WAS ISSUED NEW PAIR OF SAFETY SHOES BY THE CHIEF OFFICER.		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details :		
Date Reviewed by DPA : N/A		
Actions :		