

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

| Vessel: Asphalt Teranga | | | | | | | |
|--|-----|--|--|--|--|--|--|
| Report Date: 18-Mar-2023 | | | | | | | |
| Location: LOME TOGO | | | | | | | |
| Unsafe Act Or Condition: | | | | | | | |
| Type: Unsafe Act | | | | | | | |
| Brief Details: During maintenance work it was discovered that one crew member was not wearing hand gloves as temp of oil was high. | | | | | | | |
| Was action taken at the time? : | Yes | | | | | | |
| Was work stopped? : | Yes | | | | | | |
| Officer notified? : | No | | | | | | |
| Action successful? : | Yes | | | | | | |
| Report anonymous? : | No | | | | | | |
| Any other comments or suggestions? Enter below: | | | | | | | |
| Brief Details: All crew must wear proper PPE at workplace, There shouldn't be any short cuts taken from wearing proper PPE. | | | | | | | |
| Date Reviewed by DPA : 22-Mar-2023 | | | | | | | |
| Actions: | | | | | | | |
| Tick further Actions : No Further action required Remarks : | | | | | | | |
| Link NC/Observation/Near Miss/ Risk Assessment : | | | | | | | |
| Followup Completed: Yes | | | | | | | |

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1