



## Maritec Tanker Management

### Unsafe Act or Condition

Ship File No : N/A  
Office File No : N/A  
Form No : N/A  
Issue : N/A  
Revision : N/A  
Rev Date : N/A

|   |     |  |
|---|-----|--|
| Vessel : Bahama Blue  |     |  |
| Report Date : 23-May-2023   |     |  |
| Location : AT SEA   |     |  |
| Unsafe Act Or Condition:  |     |  |
| Type : Unsafe Condition   |     |  |
| Brief Details : This is to report you that we found rope probably belong to fishing net which was observed floated on starboard side close to front of accommodation.<br>Crew picked up the loose end of rope and tried to remove it but seems rope secured at bottom side by some anodes.<br>Presently rope secured to deck. Planning to remove it by using work boat in next convenient port. Diameter of rope about 10 mm, loose end length about 5 meters.<br>The distance from rope end to aft thrusters was about 10 m when loose rope was floating on water surface. |     |  |
| Was action taken at the time? :   | Yes |  |
| Was work stopped? :   | No  |  |
| Officer notified? :   | Yes |  |
| Action successful? :  | Yes |  |
| Report anonymous? :   | No  |  |
| Any other comments or suggestions? Enter below:   |     |  |
| Brief Details :   |     |  |
| Date Reviewed by DPA : N/A  |     |  |
| Actions :   |     |  |