



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

| | | |
|--|----------------------------|-----------|
| Vessel : Bahama Blue | | |
| Report Date : 23-May-2023 | | |
| Location : AT SEA | | |
| Unsafe Act Or Condition: | | |
| Type : Unsafe Condition | | |
| Brief Details : This is to report you that we found rope probably belong to fishing net which was observed floated on starboard side close to front of accommodation. Crew picked up the loose end of rope and tried to remove it but seems rope secured at bottom side by some anodes. Presently rope secured to deck. Planning to remove it by using work boat in next convenient port. Diameter of rope about 10 mm, loose end length about 5 meters. The distance from rope end to aft thrusters was about 10 m when loose rope was floating on water surface. | | |
| Was action taken at the time? : | Yes | |
| Was work stopped? : | No | |
| Officer notified? : | Yes | |
| Action successful? : | Yes | |
| Report anonymous? : | No | |
| Any other comments or suggestions? Enter below: | | |
| Brief Details : Good observation, Vessel manage to clear the ropes with the help of workboat. | | |
| Date Reviewed by DPA : 31-May-2023 | | |
| Actions : | | |
| Tick further Actions : | No Further action required | Remarks : |
| Link NC/Observation/Near Miss/ Risk Assessment : | | |
| Followup Completed : Yes | | |