



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bahama Blue		
Report Date : 23-May-2023		
Location : AT SEA		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : This is to report you that we found rope probably belong to fishing net which was observed floated on starboard side close to front of accommodation. Crew picked up the loose end of rope and tried to remove it but seems rope secured at bottom side by some anodes. Presently rope secured to deck. Planning to remove it by using work boat in next convenient port. Diameter of rope about 10 mm, loose end length about 5 meters. The distance from rope end to aft thrusters was about 10 m when loose rope was floating on water surface.		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details :		
Date Reviewed by DPA : N/A		
Actions :		