

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel : Biskra							
Report Date: 15-Apr-2023							
Location: Main Deck							
Unsafe Act Or Condition:							
Type: Unsafe Condition							
Brief Details: While approching Durban port a crew member noticed, hydrualic line leaking on main deck, same immediately rectified and repaired.							
Was action taken at the time? :	Yes						
Was work stopped? :	No						
Officer notified?:	Yes						
Action successful? :	Yes						
Report anonymous? :	No						
Any other comments or suggestions? Enter below:							
Brief Details : Concur with action plan.							
Date Reviewed by DPA : 21-Apr-2023							
Actions :							
Tick further Actions : No Further action required Remarks :							
Link NC/Observation/Near Miss/ Risk Assessment :							
Followup Completed: Yes							

Unsafe Act or Condition Printed On: 26-Sep-2023 1/1