



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Biskra		
Report Date : 19-Jun-2023		
Location : BRIDGE DECK		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : IT WAS OBSERVED BY DUTY OFFICER IN THE EVENING THAT THE PLATES ON THE BRIDGE DECK WERE USED AND REMAINING WERE KEPT UNLASHED. MAKING IT UNSAFE WHILE VESSEL WAS ROLLING DURING THE VOYAGE. DUTY OFFICER OBSERVE AND SAME TOLD TO DECK CREW TO LASH PROPERLY AND SECURE.		
Was action taken at the time? :	Yes	
Was work stopped? :	No	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	No	
Any other comments or suggestions? Enter below:		
Brief Details : Concur with action plan.		
Date Reviewed by DPA : 24-Jun-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		