

## Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bitu Atlantic		
Report Date: 14-Mar-2023		
Location : Deck		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details: Crew member found crossing Bunker Hose while in Bunkering Operation in progress.		
Was action taken at the time? :	Yes	
Was work stopped? :	Yes	
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details: Proper warning notice/placard must be put in place to avoid crossing charged bunker hoses.		
Date Reviewed by DPA : 17-Mar-2023		
Actions :		
Tick further Actions : No Further action required Remarks :		
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed: Yes		

Unsafe Act or Condition Printed On: 02-Aug-2023 1/1