



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 18-Apr-2023		
Location : ENGINE ROOM WORKSHOP		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : Observed tray remain with diesel oil in workshop, after cleaning filters.		
Was action taken at the time? :	Yes	Tray removed immediately.
Was work stopped? :	No	Tray removed immediately.
Officer notified? :	Yes	Explain about procedure.
Action successful? :	Yes	
Report anonymous? :	Yes	Explain about procedure.
Any other comments or suggestions? Enter below:		
Brief Details : Open oil container poses a fire hazard hence same must be kept inside closed container and away from the source of heat/ignition.		
Date Reviewed by DPA : 25-Apr-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		