

Maritec Tanker Management Unsafe Act or Condition

Ship File No : N/A Office File No : N/A Form No : N/A Issue : N/A Revision : N/A Rev Date : N/A

Vessel: Bitu Atlantic		
Report Date: 22-Apr-2023		
Location: Steering room		
Unsafe Act Or Condition:		
Type: Unsafe Condition		
Brief Details: Steering room fire door was not close properly.		
Was action taken at the time? :	Yes	Changed self door closer.
Was work stopped? :	Yes	Changed self door closer.
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details: Good observation and concur with the action plan.		
Date Reviewed by DPA : 28-Apr-2023		
Actions:		
Tick further Actions : No Fu	rther action	n required Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed: Yes		

Unsafe Act or Condition Printed On: 26-Sep-2023 1/1