

Unsafe Act or Condition

Vessel : Bitu Atlantic				
Report Date: 22-Apr-2023				
Location : Steering room				
Unsafe Act Or Condition:				
Type : Unsafe Condition				
Brief Details : Steering room fire door was not close properly.				
Was action taken at the time?	Yes	Changed self door closer.		
Was work stopped? :	Yes	Changed self door closer.		
Officer notified? :	Yes			
Action successful? :	Yes			
Report anonymous? :	Yes			
Any other comments or suggestions? Enter below:				
Brief Details : Good observation and concur with the action plan.				
Date Reviewed by DPA : 28-Apr-2023				
Actions :				
Tick further Actions : No	No Further action required		Remarks :	
Link NC/Observation/Near Miss/ Risk Assessment :				
Followup Completed : Yes				