



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Atlantic		
Report Date : 30-Jan-2023		
Location : At sea.		
Unsafe Act Or Condition:		
Type : Unsafe Act		
Brief Details : Fire and GS pump started without informing bridge.		
Was action taken at the time? :	Yes	Stopped fire pump and informed bridge.
Was work stopped? :	Yes	Stopped fire pump and informed bridge.
Officer notified? :	Yes	
Action successful? :	Yes	
Report anonymous? :	Yes	
Any other comments or suggestions? Enter below:		
Brief Details : Bridge must be kept informed whenever starting any fire pumps onboard to avoid any incidents as Bridge is kept aware of in case if any maintenance is going on in deck area.		
Date Reviewed by DPA : 03-Feb-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		