



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu Express			
Report Date : 24-Jan-2023			
Location : E/R			
Unsafe Act Or Condition:			
Type : Unsafe Act			
Brief Details : As it was defined, routine daily works/painting was carried out in Engine room and place around extinguisher was painted. To prevent damage of extinguisher, it was removed temporary from stowed position. After finishing work crew forgot to secured it back properly.			
Was action taken at the time? :	Yes		
Was work stopped? :	Yes		
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous? :	No		
Any other comments or suggestions? Enter below:			
Brief Details : All safety gears must be stowed back in position after the maintenance jobs are completed to ensure safety items are available at the time of emergency.			
Date Reviewed by DPA : 27-Jan-2023			
Actions :			
Tick further Actions :	No Further action required	Remarks :	Importance of proper securing to be discussed during next meeting.
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed : Yes			