

## **Unsafe Act or Condition**

Vessel : Bitu Express			
Report Date: 29-Jan-2023			
Location : Accomodation			
Unsafe Act Or Condition:			
Type : Unsafe Act			
Brief Details : During overall inspection by Master, Ch. OFF and CH. ENG it was observed that one Life Jacket was not in designated place in one of the crewmember's cabin.			
Was action taken at the time? :	Yes		
Was work stopped? :	Yes		
Officer notified? :	Yes		
Action successful? :	Yes		
Report anonymous? :	No		
Any other comments or suggestions? Enter below:			
Brief Details : Good observation, All safety gears must be stored in proper location so that same could be accessed easily during any emergency.			
Date Reviewed by DPA : 03-Feb-2023			
Actions :			
Tick further Actions : No Fu	: No Further action required		Importance of securing safety items to be discussed.
Link NC/Observation/Near Miss/ Risk Assessment :			
Followup Completed : Yes			