



Maritec Tanker Management

Unsafe Act or Condition

Ship File No : N/A
Office File No : N/A
Form No : N/A
Issue : N/A
Revision : N/A
Rev Date : N/A

Vessel : Bitu River		
Report Date : 06-May-2023		
Location : Break of accommodation		
Unsafe Act Or Condition:		
Type : Unsafe Condition		
Brief Details : Slight salt deposit on ship's side plate near walk way observed which made the area slight slippery.		
Was action taken at the time? :	Yes	Salt deposit mopped and removed
Was work stopped? :	No	Salt deposit mopped and removed
Officer notified? :	Yes	Chief officer informed
Action successful? :	Yes	
Report anonymous? :	No	Chief officer informed
Any other comments or suggestions? Enter below:		
Brief Details : Concur with action plan.		
Date Reviewed by DPA : 12-May-2023		
Actions :		
Tick further Actions :	No Further action required	Remarks :
Link NC/Observation/Near Miss/ Risk Assessment :		
Followup Completed : Yes		